



[Home](#)

[Banned Ships](#)

[Current Detentions](#)

[Detention Lists](#)

Inspection Database

[Appeal Procedure](#)

[Caught in the Net](#)

[Target Factor](#)

[Code of Good Practice](#)

[Expanded Inspection information](#)

[Inspection database](#) | [Inspection details](#)

MARALUNGA

Inspection details :

Date of first boarding : **24/09/2005**
Date of final boarding : **24/09/2005**
Port of inspection : **Sluiskil, Netherlands.**
Type of inspection : **Expanded inspection**
Nb of deficiency(ies) : **2**

Ship's particulars at the time of inspection :

IMO number : **9005508**
Name : **MARALUNGA**
Flag : **Italy**
Callsign : **ICIL**
Ship type : **Gas carrier**
Gross tonnage : **11361**
Keel date : **1989**

Classification society :

- Class certificate issued by Registro Italiano Navale (RINA), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- Load lines certificates is issued by Registro Italiano Navale (RINA) last survey in Spain on 13/09/2005 by Registro Italiano Navale (RINA)
- Oil pollution prevention (iopp) is issued by Registro Italiano Navale (RINA) last survey in Spain on 13/09/2005 by Registro Italiano Navale (RINA)
- Cargo ship safety construction is issued by Registro Italiano Navale (RINA) last survey in Spain on 12/09/2005 by Registro Italiano Navale (RINA)
- Liquefied gas in bulk cof/igc-code is issued by Registro Italiano Navale (RINA) last survey in Spain on 25/10/2004 by Registro Italiano Navale (RINA)
- Poll.prevent.noxious liquid subst is issued by Registro Italiano Navale (RINA) last survey in Spain on 25/10/2004 by Registro Italiano Navale (RINA)

Ship manager

- CARBONOR, 2-107, Via Gabriele d'Annunzio, Genova, Italy

Charterer

- Yara Belgium SA, 83 Avenue Marcel Thiry, Brussel, Belgium

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Operational controls carried out

- Communication equipment
- Emergency fire pump
- Emergency generator
- Emergency steering
- 15 ppm OWS tested

Deficiencies :

- Fire safety measures, Fire-dampers
- Radiocommunications, Other (radiocommunication)

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1