



[Home](#)

[Inspections](#)

[Detentions](#)

[Bannings](#)

[Appeal procedure](#)

[Target Factor](#)

[Facts & Figures](#)

[New inspection regime](#)

[Inspection Database](#)

[Inspection database](#) | [Inspection details](#)

CHEMICAL MARKETER

Inspection details :

Date of first boarding : **16/01/2007**
Date of final boarding : **16/01/2007**
Port of inspection : **Quebec City, Canada.**
Type of inspection : **More detailed inspection**
Nb of deficiency(ies) : **1**

Ship's particulars at the time of inspection :

IMO number : **9304291**
Name : **CHEMICAL MARKETER**
Flag : **Panama**
Callsign : **H3GN**
Ship type : **Chemical tanker**
Gross tonnage : **8261**
Keel date : **2003**

Classification society :

- Class certificate issued by Nippon Kaiji Kyokai (NKK), classification society responsible for issuance of class certificate as at date of first boarding

Statutory certificates :

- Cargo ship safety equipment is issued by Nippon Kaiji

Kyokai (NKK)

- Cargo ship safety radio is issued by Nippon Kaiji Kyokai (NKK)
- Tonnage certificate is issued by Nippon Kaiji Kyokai (NKK)
- Safety management certificat (SMC) is issued by Nippon Kaiji Kyokai (NKK)
- Document of compliance (DoC) is issued by Det Norske Veritas (DNVC) last survey in Hong Kong,China on 21/07/2006 by Det Norske Veritas (DNVC)
- Cargo ship safety construction is issued by Nippon Kaiji Kyokai (NKK) last survey in Italy on 21/02/2006 by Nippon Kaiji Kyokai (NKK)
- Danger.chemical bulk cof/ibc-code is issued by Nippon Kaiji Kyokai (NKK) last survey in Italy on 21/02/2006 by Nippon Kaiji Kyokai (NKK)
- Oil pollution prevention (iopp) is issued by Det Norske Veritas (DNVC) last survey in Italy on 21/02/2006 by Nippon Kaiji Kyokai (NKK)
- Load lines certificates is issued by Nippon Kaiji Kyokai (NKK) last survey in Italy on 21/02/2006 by Nippon Kaiji Kyokai (NKK)

Ship manager

- Fleet management Ltd, room 1703, 17th floor Mass Mutual tower, 38 Gloucester Road, Hong Kong, Hong Kong,China

Charterer

- CHEM-TANKERS, SAFARIWEG 50, NL-3605 MA, MAARSSSEN, Netherlands

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

Operational controls carried out

- Communication equipment
- Emergency fire pump
- Emergency generator
- Emergency steering

Deficiencies :

- Working spaces and accident prevention, Obstruction/slipping, etc.

[Back to list](#)

Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



Hosted by DSI - France - version : R1-4-1