



- [Home](#)
- [Inspections](#)
- [Detentions](#)
- [Bannings](#)
- [Appeal procedure](#)
- [Target Factor](#)
- [Facts & Figures](#)
- [New inspection regime](#)

[Inspection Database](#)

[Inspection database](#) | [Inspection details](#)

## **BOULARIBANK**

### **Inspection details :**

Date of first boarding : **21/05/2009**  
Date of final boarding : **24/05/2009**  
Port of inspection : **Berverley (Hull), United kingdom.**  
Type of inspection : **More detailed inspection**  
Nb of deficiency(ies) : **29**  
Nb of deficiency(ies) ground(s) for detention : **2**  
Duration of detention : **4 days**

### **Ship's particulars at the time of inspection :**

IMO number : **8119168**  
Name : **BOULARIBANK**  
Flag : **Antigua and Barbuda**  
Callsign : **V2PP5**  
Ship type : **Ro-ro cargo ship**  
Gross tonnage : **18663**  
Keel date : **1983**

### **Classification society :**

- Class certificate issued by Lloyd's Register (LR), classification society responsible for issuance of class certificate as at date

of first boarding

Statutory certificates :

- International Anti-fouling System Certificate is issued by Lloyd's Register (LR)
- International Air Pollution Prevention Cert is issued by Lloyd's Register (LR)
- Safety management certificat (SMC) is issued by Germanischer Lloyd (GL)
- International sewage pollution prevention certific is issued by Lloyd's Register (LR)
- Tonnage certificate is issued by Lloyd's Register (LR)
- Cargo ship safety equipment is issued by Lloyd's Register (LR)
- International ship security certificate is issued by Germanischer Lloyd (GL)
- Cargo ship safety radio is issued by Lloyd's Register (LR) last survey in Singapore on 16/04/2009 by Lloyd's Register (LR)
- Oil pollution prevention (iopp) is issued by Lloyd's Register (LR) last survey in Singapore on 15/04/2009 by Lloyd's Register (LR)
- Document of compliance (DoC) is issued by Germanischer Lloyd (GL) last survey in United Kingdom on 30/01/2009 by Germanischer Lloyd (GL)
- Cargo ship safety construction is issued by Lloyd's Register (LR) last survey in New Zealand on 09/10/2008 by Lloyd's Register (LR)
- Doc.of compliance dangerous goods is issued by Lloyd's Register (LR) last survey in New Zealand on 09/10/2008 by Lloyd's Register (LR)
- Danger.chemical bulk cof/ibc-code is issued by Lloyd's Register (LR) last survey in New Zealand on 09/10/2008 by Lloyd's Register (LR)
- Load lines certificates is issued by Lloyd's Register (LR) last survey in New Zealand on 09/10/2008 by Lloyd's Register (LR)

Ship manager

- Weir Shipping Ltd, United Kingdom

Charterer

- SWIRE PACIFIC LTD, 35 / F Two Pacific Place 88 Queensway, Central Hong Kong, Hong Kong,China

Areas inspected :

- Accommodation and galley
- Engine and steering room
- Navigation bridge
- Outside decks and forecastle

## Operational controls carried out

- Abandon ship drill
- Fire drill

## Deficiencies :

- Accident prevention (ILO147), Other (accident prevention)
- Accident prevention (ILO147), Other (accident prevention)
- Accident prevention (ILO147), Personal equipment
- Fire safety measures, Doors within main vertical zone
- Fire safety measures, Fire detection
- Fire safety measures, Fire fighting equipment and appliances
- Fire safety measures, Other (fire safety)
- Fire safety measures, Other (fire safety)
- Fire safety measures, Ready availability of fire fighting equipment
- ISM related deficiencies, Emergency preparedness, Not according SMS, ground for detention
- ISM related deficiencies, Maintenance of the ship and equipment, Not according SMS, ground for detention
- Life saving appliances , Launching arrangements for survival craft
- Life saving appliances , Launching arrangements for survival craft
- Life saving appliances , Lifeboats
- Life saving appliances , Lifeboats
- Life saving appliances , Lifebuoys
- Load lines , Doors
- Load lines , Railing, catwalks
- Load lines , Ventilators, air pipes, casings
- Load lines , Windows, side scuttles
- Maritime security, Security related defects
- Mooring arrangements (ILO 147), Other (mooring)
- Propulsion & aux., Cleanliness of engine room
- Structural safety, Emergency lighting, batteries and switches
- Structural safety, Other safety in general
- Working spaces and accident prevention, Obstruction/slipping, etc.
- Working spaces and accident prevention, Other (working space ILO)
- Working spaces and accident prevention, Safe means of access
- Working spaces and accident prevention, Safe means of access

## [Back to list](#)

## Disclaimer:

The Paris MOU (its member authorities, the secretariat and the SIRENaC manager) will not be held liable for any loss, damage, or harm resulting from the use of information contained in this database, or of any reliance on its accuracy, completeness or timeliness.



*Hosted by DSI - France - version : R1-4-1*